

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGB141LW			Page 1(4)
Author Data Daoud Attayi	Dates of Test June 12-July 04, 2013	Report No RTS-6046-1308-33	FCC ID L6ARGB140LW	

Annex E: Test set up photos

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGB141LW		Page 2(4)
Author Data Daoud Attayi	Dates of Test June 12-July 04, 2013	Report No RTS-6046-1308-33	FCC ID L6ARGB140LW

Telecoil (5, 18 mm)

Audio Output (0, 0)





Figure E1. BlackBerry Smartphone



	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGB141LW			Page 3(4)
Author Data Daoud Attayi	Dates of Test June 12-July 04, 2013	Report No RTS-6046-1308-33	FCC ID L6ARGB140LW	




Figure E2: Ambient noise and system validation measurement setup

	Document Annex E to Hearing Aid Compatibility Audio Band Magnetic (ABM) T-Coil Test Report for BlackBerry® Smartphone model RGB141LW			Page 4(4)
Author Data Daoud Attayi	Dates of Test June 12-July 04, 2013	Report No RTS-6046-1308-33	FCC ID L6ARGB140LW	




Figure E3: Audio Band Magnetic (ABM) T-Coil measurement setup