



Intertek Testing Services

ETL SEMKO

Report No.: 99009511

Tested By: Hong, Report No.: 99009511


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: X QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 99009511

Tested By: Hong, Report No.: 99009511

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A