



Report No.: 9903381

Tested By: Hong, Report No.: 9903381

Scan Settings: (2 Range)

Frequencies		Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OPRge
150K	30M	5K	10K	PK	None	AUTO	LN	OFF
			60dB					

Final Measurement: 1 QV


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
2	9K	30M	E1078

dBmV



Ctrl. No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9903381

Tested By: Hong, Report No.: 9903381

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A