



Intertek Testing Services

ETL SEMKO

Report No.: 9912671

Mode: Charging

Tested By: Hong, Report No.: 9912671

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9912671

Mode: *Charging*

Tested By: Hong, Report No.: 9912671

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

28.67500	31.3	48.0
----------	------	------

* limit exceeded

Ctrl No.: *N/A*



Intertek Testing Services

ETL SEMKO

Report No.: 9912671

Mode: Standby

Tested By: Hong, Report No.: 9912671

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	E1078



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9912671

Mode : Standby

Tested By: Hong, Report No.: 9912671

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

28.67500	32.1	48.0
----------	------	------

* limit exceeded

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 9912671

Mode: *Transmission*

Tested By: Hong, Report No.: 9912671

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl No.: *N/A*



Intertek Testing Services

ETL SEMKO

Report No.: 9912671

Made: Transmission

Tested By: Hong, Report No.: 9912671

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
-----------	----------	----------

MHz	dBuV	dBuV
-----	------	------

21.50500	27.1	48.0
----------	------	------

28.67500	33.2	48.0
----------	------	------

* limit exceeded

Ctrl No.: N/A