



Cisco Systems, Inc.
320 Springside Drive
Akron, Ohio 44333
Phone: 330 664-7900
Fax: 330-664-7922
<http://www.cisco.com>

May 30, 2002

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

RE: FCC ID: LDK102045 Attestation Statement

To Whom It May Concern:

Pursuant to Part 15.407(c) of the FCC rules addressing Unlicensed National Information Infrastructure radios, the Cisco Systems U-NII radio, FCC ID: 102044, will, via MAC layer software, automatically discontinue transmission in case of absence of information to transmit. The radio will also automatically discontinue transmission upon operational failure of the device via transmitter hardware control in instances of hardware or MAC layer software failures.

Best Regards,

A handwritten signature in blue ink, appearing to read "Jim Nicholson".

Jim Nicholson
EMC Compliance Engineer