

Mike Kuo

From: Claire Hoque
Sent: November 14, 2003 10:10 AM
To: Mike Kuo
Subject: RE: CISCO System FCC ID: LDK102051, AN03T3392 (DTS portion)

Hi Mike,

Pls see the answer as below.

Question #1: Page 1-3 of user manual indicates the antenna gain for this device is 2 dBi gain which does not agree with EMC test report and antenna specification sheet. Please explain and make necessary correction.

<Ambit>Please the attached file for LDK102051 modified.

Please note that P159 mentioned:

"The above range numbers assume that the client adapter is being used with a Cisco Aironet 1200 Series Access Point with a 2.2-dBi antenna. Different range characteristics are likely when using the client adapter with a non-Cisco access point or a Cisco Aironet 1200 Series Access Point with a different antenna."

Due to that only mentioned the range test data is done at this condition, and it did mentioned different antenna may has different result.

So we cannot change this part.

Hope this time this user's manual can be acceptable.



User

Manual(updated).pdf

Thanks,

Claire