



Cisco Systems, Inc.
4125 Highlander Parkway
Richfield, Ohio 44286
Phone: 330 523-2094
Fax: 330 523-2002
<http://www.cisco.com>

August 21, 2006

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Subject: CRN 31391 Reply
FCC ID: LDK102053 (EA826475)

To Whom It May Concern:

Question 1) Please explain/describe collocated transmitting modes of this device, including associated FCC ID(s) if applicable. Please describe testing done per 15.31h,k, and explain why if data not submitted.

Response: This device can be collocated with FCC ID LDK102049. The test results covering 15.31h and k were covered in the test report for the original submittal.

Best Regards,

A handwritten signature in blue ink, appearing to read "Jim Nicholson".

Jim Nicholson
EMC Compliance Engineer