



Cisco Systems, Inc.
4125 Highlander Parkway
Richfield, Ohio 44286
Phone: 330 523-2094
Fax: 330 523-2002
<http://www.cisco.com>

August 7, 2006

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Subject: CRN 31350 Reply
FCC ID: LDK102059 (EA481476)

To Whom It May Concern:

Question 1) You requested Modular Approval. It is my understanding that this device is to be used with specific hosts. Provide information on which host this was configured for testing.

Response: LDK102059 was configured and tested in the Cisco Systems AIR-AP1250 series host. At this time this is the only intended host for this radio module.

Best Regards,

A handwritten signature in blue ink, appearing to read "Jim Nicholson".

Jim Nicholson
EMC Compliance Engineer