

Update to Frequencies : correction of 731 form for LDK102059

5180 – 5250 MHz

5250 – 5320 MHz

5500 – 5700 MHz

5745- 5805 MHz