



Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
Phone 408 526-4000
Fax: 408 526-4100
<http://www.cisco.com>

Cisco Systems, Inc. CP-8851 Label and Location




Product Name (产品名称/Nom Du Produit) : UC Phone (UC 电话)
Model (型号/Modèle) : CP-8851
Manufacturer (制造商/Fabricant) : Cisco Systems, Inc.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

CAN ICES-3(B)/NMB-3(B)

声明：此为A级产品，在生活环境中，该产品可能会造成无线电干扰。
在这种情况下，可能需要用户对其干扰采取切实可行的措施。

2.4 DS/OF 4



US: 5B1IPNAN1076
FCC ID: LDK88511056
CANADA IC: 2461B-88511056



<http://cisco-repairs.com>



Mfg. Date (Date de fabrication):

YYYYMMDD

Made in China 中国制造

BARCODE