

Cisco Systems Inc

125 West Tasman Drive San Jose, CA 95134-1706

Tel: 408-527-7097 / Fax: 408-527-7097

Restricted band Declaration Letter

Date: 2014/11/6

FCC ID : LDKASA-AP702

We, the undersigned, attest that this device does not support operation in the 5600 - 5650 MHz Band. The firmware on the device restricts the operation in this frequency band and does not utilize the channels in this band.

FCC Grantee contact person information.

Applicant's company name : Cisco Systems Inc

Applicant's company address : 125 West Tasman Drive San Jose, CA 95134-1706

Signature :



Name and Job Title : Donn Foster GDS compliance

E-Mail : dofoster@cisco.com

Tel. : 408-853-5965