

Cisco Systems Inc

125 West Tasman Drive San Jose California United States 95134-1706

Class II Change Letter

Date: 2023/4/19

Federal Communications Commission

7435 Oakland Mills Road

Columbia MD 21046

To Whom It May Concern:

Request for Class II Permissive Change

FCC ID: LDKIW9167EH / Grant Date: 02/16/2023

Pursuant to CFR 2.1043, Cisco Systems Inc hereby requests a Class II Permissive Change.

Modification:

Update the Operation mode and FW for the device. Please refer to the sheet below. Thank you.

Original application	Operate Mode	Function	FW	Support Band
	Master	AP	WNBU image	2.4GHz, 5GHz, 4.9GHz
	Master	P2P	CURUWB image	2.4GHz, 5GHz, 4.9GHz
	Master	P2MP	CURUWB image	2.4GHz, 5GHz, 4.9GHz
Modification	Operate Mode	Function	FW	Support Band
	Master	AP	WNBU image	2.4GHz, 5GHz, 4.9GHz
	Master	P2P	CURUWB image	2.4GHz, 5GHz, 4.9GHz
	Master/Slave with radar detection	P2MP	CURUWB image	2.4GHz, 5GHz, 4.9GHz

Note

1. There is no change in hardware or in existing RF relevant portion.
2. There is no any software that can be modified by end-user.

Respectfully,

Applicant's company name : Cisco Systems Inc

Applicant's company address : 125 West Tasman Drive San Jose California United States 95134-1706

Signature : 

Name and Job Title : Adam Walb / Manager, IoT RF and Compliance

E-Mail : awalb@cisco.com

Tel : +1 408 526 4124

Fax : +1 408 526 4124