



Continental Automotive Systems, Inc.  
21440 West Lake Cook Rd  
Deer Park, IL 60010, US  
July 10, 2023

Subject: Declaration of Similarity

To whom it may concern,

We, Continental Automotive Systems, Inc., hereby declare, the similarity of HW P1.5 to HW P2 of FE3NA0031(FCC ID: LHJ-FE3NA0031, originally granted on 07/05/2022; IC ID: 2807E-FE3NA0031, originally granted on 07/07/2022):

Both HW versions present the same physical and electro mechanics characteristics.

Here are the differences between HW P1.5 to HW P2

| Change Description            | Ref-OLD | Value-OLD | REF-NEW | Value-New | Description - New                  |
|-------------------------------|---------|-----------|---------|-----------|------------------------------------|
| Replace 6.3V/0201 to 10V/0402 | C122    | 4.7u      | C122    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C304    | 4.7u      | C304    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C306    | 4.7u      | C306    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C307    | 4.7u      | C307    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C308    | 4.7u      | C308    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C309    | 4.7u      | C309    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C310    | 4.7u      | C310    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C311    | 4.7u      | C311    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C313    | 4.7u      | C313    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C314    | 4.7u      | C314    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0201 to 10V/0402 | C319    | 4.7u      | C319    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |
| Replace 6.3V/0402 to 10V/0603 | C327    | 22u       | C327    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0402 to 10V/0603 | C328    | 22u       | C328    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0402 to 10V/0603 | C329    | 22u       | C329    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0402 to 10V/0603 | C330    | 22u       | C330    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0402 to 10V/0603 | C331    | 22u       | C331    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0402 to 10V/0603 | C332    | 22u       | C332    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0402 to 10V/0603 | C333    | 22u       | C333    | 22u       | C CER,X5R,22 uF,20%,10.0 V,EC_0603 |
| Replace 6.3V/0201 to 10V/0402 | C447    | 4.7u      | C447    | 4.7u      | C CER,X5R,4.7uF,20%,10V,0402       |

We declare also that all the functionality and purposes of the products are exactly the same.



Sincerely,

A handwritten signature in black ink, appearing to be "JZ", written over a dashed horizontal line.

Jianming Zhang

LTE and 5G NAD Manager