
INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)




FCC ID: LIV-RTPGRXV2
IC: 7032A-RTPGRXV2

INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)




INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)



INTERTEK TESTING SERVICE

Report No.: 16061417HKG-001/002

Equipment Photographs

(Internal)

