

Kare Oksanen

25th Oct 2004

1. FYI - Please note the part 15 block diagrams are to have the clock frequencies and paths located on the diagram. No action is required at this time as the first page of the schematics is a reasonable addition to the block diagram as it gives frequencies.

Acknowledged.

2. Please note that it is not clear where on the device the Bluetooth transmitter is located. It appears as if the BT rf section is in the lower left corner of the first photo on page 4 of the internal photo exhibit, however this is not known. Please clearly identify the BT rf section on the internal photos. Also, there appears to be a shielded area on the board just to the left of the section mentioned above. Is this the memory card slot shown in the manual? Please clarify.

I have now uploaded new internal photograph, which identifies BT section. We also confirm that metallic plate right of the BT section is MMC/SD card reader slot, not a shield.

3. Please note that while you have provided a confidentiality request for Industry Canada, no request for FCC confidentiality IAW 0.459 has been provided. If FCC confidentiality is requested, please provide a confidentiality request letter IAW 0.459 of CFR 47.

This document was accidentally left out. It is now uploaded into your server.

4. FYI – as this is a Bluetooth device operating under 2mW, you can remove the non-collocation statement from the manual if desired.

We will remove this statement in the future revision.