

Intersil Corporation

P.O. Box 343  
3720 AH Bilthoven  
The Netherlands  
Rembrandtlaan 1a  
3723 BG Bilthoven  
The Netherlands

telephone +31 (0)30 229 60 60  
facsimile +31 (0)30 229 60 61

**intersil**

Date: 01 May 2003

Our reference  
2002-mansup-525-5

Subject: Permission for Actiontec to use Intersil  
Documentation

To:  
**Bay Area Compliance Lab. Corp.**  
**TCB dept.**  
**230 Commercial Street, Sunnyvale,**  
**CA 94086, USA**  
**Phone: 408-732-9162**  
**Fax: 408-732-9164**

Dear TCB,

Intersil Corp. hereby grants permission to:

|                      |                             |
|----------------------|-----------------------------|
| <b>Company</b>       | Actiontec Electronics, Inc. |
| <b>Address, City</b> | 760 North Mary Ave.,        |
| <b>Country</b>       | Sunnyvale, CA 94086 USA     |
| <b>Phone number</b>  | 408-752-7700                |
| <b>Fax number</b>    | 408-732-0087                |

to use Intersil model: **ISL38000C (FCC ID: OSZ38000C)** documentation for FCC, ETSI and other regulatory certification purposes for the following product:

|                     |                                |
|---------------------|--------------------------------|
| <b>FCC ID</b>       | LNQ802CIG                      |
| <b>Brand</b>        | Actiontec                      |
| <b>Model number</b> | 802CIG                         |
| <b>Description</b>  | IEEE 802.11g WLAN Cardbus Card |

This permission is only valid for using the documentation for the above mentioned Intersil model **ISL38000C (FCC ID: OSZ38000C)** and expires on November 1st, 2003.

Yours sincerely,



Derick Sariredjo ( derick.sariredjo@intersil.com )  
Manufacturing Support / Regulatory Office

Intersil Corp. The Netherlands ( www.intersil.com )  
Rembrandtlaan 1a  
3723 BG Bilthoven, The Netherlands  
Phone: +31.30.225.9742  
Mobile: +31.62.732.8048  
Fax: +31.30.229.6061

**www.intersil.com**  
ING Bank: 65.02.63.049  
Swift code: INGBNL2A  
VAT / BRW: NL8039.66.659.B.01  
Chamber of Commerce Utrecht: 30139807