

IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (chain 2)
5530MHz

Date: 30 JUL 2019 15:26:59

5610MHz

Date: 30 JUL 2019 15:28:23

5690MHz



Date: 30 JUL 2019 15:57:50

IEEE 802.11ac VHT80 Mode / 5250 ~ 5350MHz (chain 3)
5530MHz

Date: 30 JUL 2019 15:26:46

5610MHz



Date: 30 JUL 2019 15:28:37

5690MHz



Date: 30 JUL 2019 15:59:18


UNII-3 Band IV PSD**IEEE 802.11a mode / 5725 ~ 5850MHz (chain 0)****5745MHz**

Date: 30 JUL 2019 16:41:57

5785MHz

Date: 30 JUL 2019 16:49:00


5825MHz



Date: 30 JUL 2019 16:52:03


IEEE 802.11a mode / 5725 ~ 5850MHz (chain 1)

5745MHz




Date: 30 JUL 2019 16:40:12

5785MHz



Date: 30 JUL 2019 16:48:50

5825MHz



Date: 30 JUL 2019 16:51:49


IEEE 802.11a mode / 5725 ~ 5850MHz (chain 2)

5745MHz



Date: 30 JUL 2019 16:41:31

5785MHz



Date: 30 JUL 2019 16:48:20

5825MHz



Date: 30 JUL 2019 16:51:36

IEEE 802.11a mode / 5725 ~ 5850MHz (chain 3)

5745MHz




Date: 30 JUL 2019 16:40:32

5785MHz




Date: 30 JUL 2019 16:48:02


5825MHz



Date: 30 JUL 2019 16:51:19


IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 0)
5745MHz

Date: 30 JUL 2019 16:55:19


5785MHz

Date: 30 JUL 2019 16:57:10

5825MHz



Date: 30 JUL 2019 16:53:38

IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 1)
5745MHz

Date: 30 JUL 2019 16:55:00

5785MHz



Date: 30 JUL 2019 16:56:44

5825MHz



Date: 30 JUL 2019 16:53:17


IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 2)
5745MHz

Date: 30 JUL 2019 16:54:43


5785MHz

Date: 30 JUL 2019 16:56:25

5825MHz




Date: 30 JUL 2019 16:53:02

IEEE 802.11ac VHT20 Mode / 5725 ~ 5850MHz (chain 3)
5745MHz

Date: 30 JUL 2019 16:54:30

5785MHz




Date: 30 JUL 2019 16:56:13


5825MHz




Date: 30 JUL 2019 16:52:49

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 0)
5755MHz


Date: 30 JUL 2019 16:31:19

5795MHz


Date: 30 JUL 2019 16:36:46

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 1)
5755MHz


Date: 30.JUL.2019 16:30:16

5795MHz


Date: 30.JUL.2019 16:36:34

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 2)
5755MHz


Date: 30 JUL 2019 16:31:02

5795MHz

Date: 30 JUL 2019 16:36:08

IEEE 802.11ac VHT40 Mode / 5725 ~ 5850MHz (chain 3)
5755MHz


Date: 30 JUL 2019 16:24:27

5795MHz

Date: 30 JUL 2019 16:35:51

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 0)

5775MHz



Date: 30.JUL.2019 16:23:05

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 1)

5775MHz



Date: 30.JUL.2019 16:22:53

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 2)


5775MHz



Date: 30.JUL.2019 16:22:42

IEEE 802.11ac VHT80 Mode / 5725 ~ 5850MHz (chain 3)

5775MHz



Date: 30.JUL.2019 16:22:29

***** END OF REPORT *****