



Intertek Testing Services

ETL SEMKO

Report No.: 0000124

Tested By: Hong, Report No.: 0000124

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----||

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	E1078



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0000124

Tested By: Hong, Report No.: 0000124

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start Stop Step IF BW Detector M-Time Atten Preamp OpRge

450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency QP Level QP Limit

MHz dBuV dBuV

0.46500 40.6 48.0

0.65000 39.8 48.0

0.87000 35.3 48.0

1.42500 33.4 48.0

1.79500 31.3 48.0

2.23000 27.1 48.0

9.98500 25.9 48.0

* limit exceeded

Ctrl No.: N/A