



Intertek Testing Services

ETL SEMKO

Report No.: 9913333

Tested By: Hong, Report No.: 9913333

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP


Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

dBuV



PAGE 1

Ctrl No.: NA



Report No.: 9913333

Tested By: Hong, Report No.: 9913333

Scan Settings (1 Range)

----- Frequencies ----- | ----- Receiver Settings ----- |

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results