

Appendix N: Internal Photographs



Photograph 11: Front with Shield

Client: Hunter Engineering Co.
Model/HVIN: 45-1549
Standards: FCC 15.247
IDs: LS3-45-1549/2938A-451549
Report #: 2016038DXT





Hunter 45-1549 FCC and IC Label Silkscreen

Photograph 13: Back View