

INTERTEK TESTING SERVICE

Report No.: 15040508HKG-004

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15040508HKG-004

Equipment Photographs

(Internal)





FCC ID: LU9638541RX
IC: 4504A-638541RX

INTERTEK TESTING SERVICE

Report No.: 15040508HKG-004

Equipment Photographs

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15040508HKG-004

Equipment Photographs

(Internal)





FCC ID: LU9638541RX
IC: 4504A-638541RX

INTERTEK TESTING SERVICE

Report No.: 15040508HKG-004

Equipment Photographs

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15040508HKG-004

Equipment Photographs

(Internal)

