

INTERTEK TESTING SERVICE



Report No.: 15040508HKG-001

Equipment Photographs

Model : 638541 (FCC)

638541E4C(TX) (IC)

(Internal)



FCC ID: LU9638541TX

IC: 4504A-638541TX



INTERTEK TESTING SERVICE

Report No.: 15040508HKG-001

Equipment Photographs

Model : 638541 (FCC)
638541E4C(TX) (IC)

(Internal)



FCC ID: LU9638541TX

IC: 4504A-638541TX



INTERTEK TESTING SERVICE

Report No.: 15040508HKG-001

Equipment Photographs

Model : 638541 (FCC)
638541E4C(TX) (IC)

(Internal)



FCC ID: LU9638541TX

IC: 4504A-638541TX



INTERTEK TESTING SERVICE

Report No.: 15040508HKG-001

Equipment Photographs

Model : 638541 (FCC)
638541E4C(TX) (IC)

(Internal)



FCC ID: LU9638541TX

IC: 4504A-638541TX


INTERTEK TESTING SERVICE

Report No.: 15040508HKG-001

Equipment Photographs

**Model : 638541 (FCC)
638541E4C(TX) (IC)**

(Internal)



FCC ID: LU9638541TX

IC: 4504A-638541TX

INTERTEK TESTING SERVICE

Report No.: 15040508HKG-001

Equipment Photographs

**Model : 638541 (FCC)
638541E4C(TX) (IC)**

(Internal)

