




2577.5 MHz_15M_QPSK_1RB_Below 1GHz




2577.5 MHz_15M_QPSK_1RB_Above 1GHz




2595.0 MHz_15M_QPSK_1RB_Below 1GHz




2595.0 MHz_15M_QPSK_1RB_Above 1GHz




2612.5 MHz_15M_QPSK_1RB_Below 1GHz




2612.5 MHz_15M_QPSK_1RB_Above 1GHz




2580.0 MHz _20M_QPSK_1RB_Below 1GHz




2580.0 MHz _20M_QPSK_1RB_Above 1GHz




2595.0 MHz _20M_QPSK_1RB_Below 1GHz




2595.0 MHz _20M_QPSK_1RB_Above 1GHz




2610.0 MHz _20M_QPSK_1RB_Below 1GHz




2610.0 MHz _20M_QPSK_1RB_Above 1GHz




Mode 10: LTE Band 41

2501.0 MHz_10M_QPSK_1RB_Below 1GHz




Date: 16.AUG.2024 10:04:34

2501.0 MHz_10M_QPSK_1RB_Above 1GHz




Date: 16.AUG.2024 10:04:44

2593.0 MHz_10M_QPSK_1RB_Below 1GHz




Date: 16.AUG.2024 10:05:41

2593.0 MHz_10M_QPSK_1RB_Above 1GHz




Date: 16.AUG.2024 10:05:50

2685.0 MHz_10M_QPSK_1RB_Below 1GHz



Date: 16.AUG.2024 10:10:41

2685.0 MHz_10M_QPSK_1RB_Above 1GHz



Date: 16.AUG.2024 10:10:55