











Active Low Wake Ups




Active Low Wake Ups




Active Low Wake Ups




Octal Lowside - Spare 1 & 2, Internal Run Start, BACC, Pulse Train, VSPD, & Rear Seat Recline




Octal Lowside - PP Relay, Horn, Trailer Tow, External Run Start, & Fuel Pump









Octal Configurable







Lip Bone Supply and Clear



Piezo Sounder






Door Lock ASUC





Continental Confidential Level II

Document	Revision	Date	Author	Checker	Appr.
ASUC	1.0	2000-01-01	Continental	Continental	Continental
ASUC	1.1	2000-01-01	Continental	Continental	Continental
ASUC	1.2	2000-01-01	Continental	Continental	Continental
ASUC	1.3	2000-01-01	Continental	Continental	Continental
ASUC	1.4	2000-01-01	Continental	Continental	Continental
ASUC	1.5	2000-01-01	Continental	Continental	Continental
ASUC	1.6	2000-01-01	Continental	Continental	Continental
ASUC	1.7	2000-01-01	Continental	Continental	Continental
ASUC	1.8	2000-01-01	Continental	Continental	Continental
ASUC	1.9	2000-01-01	Continental	Continental	Continental
ASUC	2.0	2000-01-01	Continental	Continental	Continental

[illegible]

JTAG CONNECTOR



Equipment	Preparation	Chase yield	Chase type - chemical light loss - 1 hour 20 days - none
-----------	-------------	-------------	--

1.4	CAD-Bytes: 00000	01 : 2014-02
-----	------------------	--------------

