

Company: Polycom Inc

Product Name: Trio 8500

Report No.: POLY35 - Leaf Basic FCC IC EU Japan AUS
NZ

PHOTOS - INTERNAL




1. Internal Photographs


1.1.1. Product - Internal




Front Arm




Front Arm Button Bottom



Front Arm Button Top




Front Arm PCB Bottom



Front Arm PCB Top




Title: Polycom Inc Trio 8500
To:
Serial #: POLY35 Internal Photos
Issue Date: 24 July 2017
Page: 7 of 23




Left Arm


This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



Left Arm Button Bottom




Left Arm Button Top



Left Arm PCB Bottom




Title: Polycom Inc Trio 8500
To:
Serial #: POLY35 Internal Photos
Issue Date: 24 July 2017
Page: 11 of 23




Left Arm PCB Top

This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.



RF Board Bottom



RF Board Top




Title: Polycom Inc Trio 8500
To:
Serial #: POLY35 Internal Photos
Issue Date: 24 July 2017
Page: 14 of 23




Right Arm


This test report may be reproduced in full only. The document may only be updated by MiCOM Labs personnel. All changes will be noted in the Document History section of the report.




Right Arm Button Bottom




Right Arm Button Top



Right Arm PCB Bottom with Shields




Right Arm PCB Bottom without Shields



Right Arm PCB Top



USB Board Bottom



Whole Product View



575 Boulder Court
Pleasanton, California 94566, USA
Tel: +1 (925) 462 0304
Fax: +1 (925) 462 0306
www.micomlabs.com