



HP Inc.  
1501 Page Mill Road,  
Palo Alto, CA 94304  
USA  
www.hp.com

## DFS client device channel plan and software operational declaration

Date: 2025-12-02

We, **HP Inc.**, declare that the device, FCC ID: **M72-EDV650** Model Name: **PVAN-EDGE-V650**, does not have Ad Hoc on “non-US frequencies” and/or on “DFS frequencies”. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

### 2.4GHz

| CH              | 1      | 2      | 3      | 4      | 5      | 6      | 7      | 8      | 9      | 10     | 11     |
|-----------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Frequency (MHz) | 2412   | 2417   | 2422   | 2427   | 2432   | 2437   | 2442   | 2447   | 2452   | 2457   | 2462   |
| Scan Type       | Active | Active | Active | Active | Active | Active | Active | Active | Active | Active | Active |

### 5GHz B1

| CH              | 36     | 40     | 44     | 48     |  |  |  |  |
|-----------------|--------|--------|--------|--------|--|--|--|--|
| Frequency (MHz) | 5180   | 5200   | 5220   | 5240   |  |  |  |  |
| Scan Type       | Active | Active | Active | Active |  |  |  |  |

### 5GHz B2

| CH              | 52      | 56      | 60      | 64      |  |  |  |  |
|-----------------|---------|---------|---------|---------|--|--|--|--|
| Frequency (MHz) | 5260    | 5280    | 5300    | 5320    |  |  |  |  |
| Scan Type       | Passive | Passive | Passive | Passive |  |  |  |  |

### 5GHz B3

| CH              | 100     | 104     | 108     | 112     | 116     | 120     |
|-----------------|---------|---------|---------|---------|---------|---------|
| Frequency (MHz) | 5500    | 5520    | 5540    | 5560    | 5580    | 5600    |
| Scan Type       | Passive | Passive | Passive | Passive | Passive | Passive |
| CH              | 124     | 128     | 132     | 136     | 140     | 144     |
| Frequency (MHz) | 5620    | 5640    | 5660    | 5680    | 5700    | 5720    |
| Scan Type       | Passive | Passive | Passive | Passive | Passive | Passive |

### 5GHz B4

| CH              | 149    | 153    | 157    | 161    | 165    |
|-----------------|--------|--------|--------|--------|--------|
| Frequency (MHz) | 5745   | 5765   | 5785   | 5805   | 5825   |
| Scan Type       | Active | Active | Active | Active | Active |

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before



HP Inc.  
1501 Page Mill Road,  
Palo Alto, CA 94304  
USA  
[www.hp.com](http://www.hp.com)

firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed.

Sincerely yours,

A handwritten signature in black ink, appearing to read 'Yuk Wan', written over a light gray rectangular background.

-----  
Yuk Wan,  
Manager, Product Compliance  
[HP Inc.](#)  
Tel: (+44) 1753 723174  
E-mail: [yuk.wan@hp.com](mailto:yuk.wan@hp.com)