

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 19061029HKG-001, 19061029HKG-004
FCC ID: M72-VVX230
IC: 1849C-VVXD230



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 19061029HKG-001, 19061029HKG-004
FCC ID: M72-VVX230
IC: 1849C-VVXD230

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 19061029HKG-001, 19061029HKG-004
FCC ID: M72-VVX230
IC: 1849C-VVXD230

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 19061029HKG-001, 19061029HKG-004
FCC ID: M72-VVX230
IC: 1849C-VVXD230

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 19061029HKG-001, 19061029HKG-004
FCC ID: M72-VVX230
IC: 1849C-VVXD230



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos

