

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 19061029HKG-002, 19061029HKG-005
FCC ID: M72-VVXD230
IC: 1849C-VVXD230H

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 19061029HKG-002, 19061029HKG-005
FCC ID: M72-VVXD230
IC: 1849C-VVXD230H

INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 19061029HKG-002, 19061029HKG-005
FCC ID: M72-VVXD230
IC: 1849C-VVXD230H

INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 19061029HKG-002, 19061029HKG-005
FCC ID: M72-VVXD230
IC: 1849C-VVXD230H

INTERTEK TESTING SERVICES

Internal photos

