LABEL AND LABEL LOCATION

FIRST ALERT

MODEL SMCO500V

Single and/or Multiple Station Smoke Alarm & Carbon Monoxide Alarm
Powered with 2 AA Duracell MN1500 Batteries. Smoke Sensitivity: 2.3%/ft. obs +- 25%

WARNING!

CARBON MONOXIDE CANNOT BE SEEN OR SMELLED BUT CAN KILL YOU.

IF ALARM SIGNAL SOUNDS:

1. OPERATE TEST / SILENCE BUTTON.
2. CALL YOUR EMERGENCY SERVICES (FIRE DEPARTMENT OR 911).
3. IMMEDIATELY MOVE TO FRESH AIR – OUTDOORS OR BY AN OPEN DOOR / WINDOW.

ALARM WILL NOT OPERATE IF BATTERIES ARE DEAD, DISCONNECTED OR IMPROPERLY INSTALLED. REFER TO USER'S MANUAL FOR COMPLETE BATTERY REPLACEMENT LIST, INSTALLATION, OPERATING AND SAFETY INFORMATION / INSTRUCTIONS. USE ONLY BATTERIES SPECIFIED. USE OF OTHER BATTERIES MAY HAVE A DETRIMENTAL EFFECT ON PRODUCT OPERATION. CONSTANT USE AT HIGH OR LOW TEMPERATURE OR HIGH HUMIDITY MAY REDUCE BATTERY LIFE.

IMPORTANT!

ALARM AUTOMATICALLY COMMUNICATES WITH COMPATIBLE WIRELESS INTERCONNECT ENABLED ALARMS. REFER TO USER'S MANUAL FOR MORE INFORMATION.

FCC ID: M7U-500V1

This device complies with part 15 of the FCC rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

CARBON MONOXIDE SENSITIVITY

CO LEVEL (PPM)	70	150	400
RESPONSE TIME (MIN)	60 - 240	10 - 50	4 - 15

Manufactured PRODUCTION DATE FPO

Installed On _____

Replace By _____

REPLACE ALARM 10 YEARS AFTER INSTALLATION

MAINTENANCE:

Gently vacuum or use clean compressed air to remove accumulated dust monthly. Never use water, cleaners or solvents, since they may damage the unit. Press the test button after installation, weekly and after cleaning to check all alarm functions.

ALARM GUIDE:

3 Beeps – Smoke Alarm
4 Beeps – CO Alarm
1 "Chirp" every 45 seconds – Replace Battery
3 "Chirps" every 45 seconds – Malfunction – Replace Alarm
5 "Chirps" every 45 seconds – End of Life – Replace Alarm

FOR "VOICE" INSTRUCTIONS – SEE MANUAL

ETL LISTED US

Intertek
3055574

Conforms to UL STD 217 and UL STD 2034

Helps reduce cooking nuisance alarms

PHOTOELECTRIC

WIRELESS INTERCONNECT ENABLED ALARM

FC

Follow and retain user's manual
Customer Service Team: 1-800-323-9005
Resideo Technologies, Inc. and its Affiliates
1301 Joe Battle, El Paso, TX, 79936 USA
Made in Mexico

firstalert.com

N04-171588-005

Figure 1 Label

Figure 2 Label location