



Dear Sirs / Madam

The manufacturer, MITAC TECHNOLOGY CORP., modified their Notebook PC (FCC ID MAU008) but they wish to continue using the same FCC ID.

The changed parts are listed below

1. Change the ADI 12.1" TFT LCD to Hyundai 12.1" TFT LCD.
2. Change the MMC2 Module Processor to gPGA2 / BGA2 package.
3. Change the LAN BD chip RTL8139B to RTL8139C and the LAN board relayout.

We have already tested the modified product and attached the test report. If you have any question, please feel free to contact with us. Thank you very much.

Sincerely,

Alice Duan

ERSO/ITRI