


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone TDMA INPT OUT OF RACK
FFPA-8689-120 + FFPA-869-60

Tested By: B De V 10/1/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932


Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone TDMA OUTPUT AMPLIFIER
FFPA-8869-120 OUT OF GAY

Tested By: R. Laporte 10/14/99




Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120




Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: Single Tone ZFSK input both Amplifiers
FFPA-8689-60 and FFPA-8689-120

Tested By: Brian Papadakis 10/4/99


Project Number: 99ME45100

Issue Date: November 19, 1999

File Number: NC3932

Model: FFPA-8689-120 (Amplifier) and HPC8689-400 (Shelf)

FCC ID: MCD FFPA8689-120



Observations/Comments: SINGLE TONE 2FSK OUTPUT AMPLIFIER

FFPA-8689-120 OUT OF BAND

Tested By: Berni Paprocki 10/4/99