






















01


02

2y-2 94V-0 RJ E319

1. This device may not cause harmful interference.
2. This device must accept any interference received,
including interference that may cause undesired operation.

FCC ID: MFG30004
Use AA Batteries only
This device complies with Part 15 of the FCC rules.
Operation is subject to the following two conditions:
1. The device must not cause harmful interference.
2. The device must accept any interference received,
including interference that may cause undesired operation.

60212-4187000 V00
MFG30004 remote transceiver
Hospitality Remote 2015
URC-3018CC0-X-R
JUN 2016



Zy-2 94V-0

9508

1. This device may not cause harmful interference.
2. This device must accept any interference received, including interference that may cause undesired operation.

FCC ID:MG33004
Use AA Batteries only
This device complies with Part 15 of the FCC rules.
Operation is subject to the following two conditions:

60212-4187000 V00
UCI DIRECTV ROOMB Cleanable
Hospitality Remote 2015
URC-3018BC0-X-R
JUN.2016