

Scott McCutchan

From: Scott McCutchan [scott@celectronics.com]
Sent: Monday, January 06, 2003 12:43 PM
To: kyle@celectronics.com
Subject: FCC ID: MG3URC033

Mr. Fujimoto,

In order for processing of this application (FCC ID: MG3URC033) to continue, the following issue(s) will have to be addressed:

- 1) The FCC ID on the label does not meet the requirements of CFR 47, Part 2, Section 2.925(a)(1). The term "FCC ID" must be on the same line as the actual identifier.
- 2) The fundamental and harmonic data contained within the test report appears to be corrupted. Please submit a new set of data.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Please upload your response to our electronic filing website using a correspondance number of "MG3URC033-1".

If you have any questions, feel free to contact me.

Best regards,

Scott McCutchan
Operations Manager
Compatible Electronics TCB
(714) 579-1489
fax (714) 579-1850
<http://www.celectronics.com>

Correspondence by Project

Project Number:

1860617400

Correspondence Number	Memo
MG3URC033-1	1. The FCC-ID Label has been revised to show the term "FCC ID" on the same line as the actual identifier. Please see the revised FCC-ID Label in the exhibits. 2. Appendix E of the test report (the data sheets) have been re-uploaded as a separate exhibit. This is due to the fact the computer corrupts the data when we try to sign electronically, and scanning in the page with the signatures would cause the file to exceed 4 MB. Appendix E will be 17 pages and include all of the data contained.