

2.1033(c)(9) TUNE-UP PROCEDURE

There is no tune-up procedure required over the power range or at specific operating power levels because the unit is software controlled.