



Enfora L.P.
661 E. 18th Street
Plano, TX 75074-5601
(972) 633-4400
Fax (972) 633-4444

July 8, 2004

RE: Enfora GSM3208, Question Regarding GPRS Operating Mode

Reviewing FCC Engineer,

We have reviewed our published data sheets for the GSM3208 regarding the Multi-Slot Class of operation and they are in error. The brochure states "Multislot Class: MS10". This is incorrect and will be corrected next week.

The brochure will be corrected to state "Multislot Class: MS-8".

We do not operate this device in MS-10 mode due to a significant decrease in battery life and the lack of need for the PDA to send large amounts of data. The software supplied with the GSM3208 does not have the capability to modify the Multi-Slot Class.

I have reviewed our documentation regarding the testing of the GSM3208. The GSM3208 uses an Enfora GSM0108 Quad-Band Modem. During the final factory test of the GSM3208, the Multi-Slot class is verified as MS-8.

I am attaching pages 1 & 6 of our **confidential** GSM3208MG000TRD (Test Requirements Document). On page 6, note the line that starts "\$MSCLS: 8". That confirms that the modem is set to MS-8 operation.

I am also attaching the definition of that particular AT Command that sets/reads the MS Class.

Sorry for the confusion. Let me know if you have any other questions.

Regards,

A handwritten signature in black ink that reads "Scott Yarberry". The signature is written in a cursive, flowing style.

Scott

Scott Yarberry
Sr. Director, Product Development
Enfora L.P.
661 E. 18th St.
Plano, TX 75074
972.633.3560
syarberry@enfora.com