

Attachment:

- Front page of the Manual
- "FCC Compliance Statement"

engineer:		date:	
J. Luttner		December 19 th , 1998	
no.:	sign:	O.K.	



Applicant for this device:	
ICP vortex Computersysteme GmbH SCSI-Controller GDT6518RD	
FCC ID:	side:
MJLMONA6X18RD	30/30

User Manual



GDT RD Series

PCI - Fibre Channel
Disk Array Controllers

ICP
Intelligent Computer Peripherals[®]

ICP vortex Computersysteme GmbH
Falterstr. 51-53
74223 Flein, Germany

Tel: +49-7131-5972-0
Fax: +49-7131-255063
BBS: +49-7131-5972-15
<http://www.icp-vortex.com>
e-mail: info@vortex.de

ICP vortex Corporation
4857 West Van Buren Street
Phoenix, AZ 85043, USA

Phone: (602) 353-0303
Fax: (602) 353-0051
<http://www.icp-vortex.com>
e-mail: sales@icp-vortex.com

ICP
Intelligent Computer Peripherals[®]

C o m p e t e n c e i n C o n t r o l l e r s

CC Compliance Statement

Information for the User

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in residential installations. This equipment generates, uses, and can radiate radio frequency energy, and if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to correct the interference by one or more of the following measures:

- Reorientate or relocate the receiving antenna.

- Increase the separation between the equipment and the receiver.

- Plug the equipment into an outlet on a circuit different from that to which the receiver is powered.

- If necessary, consult the dealer or an experienced radio/TV technician for additional suggestions.

The use of a non-shielded interface cable with the referenced device is prohibited. Changes or modifications not expressly approved by ICP vortex Computersysteme GmbH would void the authority to operate the equipment.

Kapitel A

Allgemeine

Informationen