

Attachment:

- Front page of the Manual
- "FCC Compliance Statement"

engineer:		date:		Applicant for this device:	
J. Luttner		December 21 st , 1998		ICP vortex Computersysteme GmbH	
no.:	sign:	O.K.		SCSI-Controller GDT6538RD	
				FCC ID:	
				M.II MONA6X38RD	
				side:	
				30/30	




User's Manual



GDT RD Series

PCI - Fibre Channel
Disk Array Controllers



Intelligent Computer Peripherals®

ICP vortex Computersysteme GmbH
Falterstr. 51-53
74223 Flein, Germany

Tel: +49-7131-5972-0
Fax: +49-7131-255063
BBS: +49-7131-5972-15
<http://www.icp-vortex.com>
email: info@vortex.de

ICP vortex Corporation
4857 West Van Buren Street
Phoenix, AZ 85043, USA

Phone: (602) 353-0303
Fax: (602) 353-0051
<http://www.icp-vortex.com>
email: sales@icp-vortex.com



C o m p e t e n c e i n C o n t r o l l e r s

Compliance Statement

Information for the User

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in residential installations. This equipment generates, uses, and can radiate radio frequency energy, and if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

Reorientate or relocate the receiving antenna.

Increase the separation between the equipment and the receiver.

Plug the equipment into an outlet on a circuit different from that to which the receiver is connected.

If necessary, consult the dealer or an experienced radio/TV technician for additional suggestions.

Use of a non-shielded interface cable with the referenced device is prohibited.

Changes or modifications not expressly approved by ICP vortex Computersysteme GmbH void the authority to operate the equipment.

Kapitel A

Allgemeine

Informationen