

Report No.: 99001971

Tested By: Hong, Report No.: 99001971

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----


Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Final Measurement: X QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

dBuV



Ctrl. No.: N/A

Report No.: 99001971

Tested By: Hong, Report No.: 99001971

Scan Settings (1 Range)

|----- Frequencies -----|----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
0.45000	24.0	48.0

* Limit exceeded

Ctrl. No.: N/A