

Date: January 13, 2026

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To Whom It May Concern:

This Class II permissive change request applies for an FCC ID: MRBSATEL-TA43.

Radio modem module's power amplifier and related peripheral components have been changed due to power amplifier EOL.

Further details and supporting documents are attached.

Should there be any question, please feel free to contact us.

Sincerely,



Pekka Suominen

Certification Engineer

SATEL Oy

SATEL

MISSION-CRITICAL CONNECTIVITY

Meriniitynkatu 17, P.O. Box 142
24101 Salo, FINLAND
Tel. +358 2 777 7800
info@satel.com www.satel.com