

SW2

XTAL

U3

R17

R10

C2

C1

R1

C20

U1

C4

C5

C6

C3

R2

C19

R12

R16

C8

C7

C10

R3

C11

C12

R6

L1

C14

R9

R7

C17

L3

Q1

R4

L2

Q2

C13

C16

C15

R8

R5

C9

TPND

RES

C18

SW1

