





RTS5117
5C3510Z
L601CC TAIWAN
e12.000
FB3zE
ASUS
DE IN TAIWAN
BOARD REV:1.2








4R7
05279
32C58
15
1E5N
H18
H17
0601 4



ITE
IT8510TE
0545-GXA
32C58
X8
JP6
14.3F4E
100 P
50LN e
100 P
50LN e


intel
NH82801GBM
F5433469
SL8YB
PHILIPPINES


ICS
81C-200
0535
954310BGLF




MW772L
SH001B
RTL8111B
e25.000
FB3JE



SUNON
GC054509VH-A
P/N:13.82239.F.GN
060118
DC5V


R1F
SAMPLE
S060119R


Seagate
Momentus 5400.2
120 GB
This drive is manufactured by Seagate for OEM distribution. For product information or technical support, please contact your system OEM.
CAUTION: Avoid excessive shock; do not push on top cover or remove any seal or label.
SN: 3PL0CST1
Model: ST9120821AS
PN: 9W3184-502
FW: 3.04
Date: 06322
Site: AMK
+5V 0.48 A
Data
Power


FG6311M0K
15615


HITACHI
Travelstar™
www.hitachigst.com
RoHS
MODEL:HTS541010G9SA00
5V 0A DC
MADE IN THAILAND BY Hitachi Global
Storage Technologies(Thailand) Ltd
WARRANTY VOID IF ANY LABEL/
SCREW IS REMOVED OR BROKEN
JAN-06
P/N:0A26930
(16383CYL, 16HEADS, 63SEC/T)
MLC:DA1265
0A26930DA12650P61
S/N:X0H9R87R
DO NOT COVER
THIS HOLE ⇒
Don't shock/
push cover




FUJITSU
SERIAL ATA
DO NOT COVER
RoHS compliance


HALOGEN-FREE PWB
R160031JA
CA26338-B74104BA
CA21338-B74
4030C
05Z01027108


FUJITSU
DO NOT COVER
RoHS compliance


HALOGEN-FREE PWB
R16026JA
CA26338-B74104BA
CA21338-B74X


HITACHI
Travelstar TM
www.hitachigst.com
RoHS
MODEL: HTS541080G9SA00
5V 1.0A DC
MADE IN THAILAND BY Hitachi Global
Storage Technologies(Thailand),Ltd.
WARRANTY VOID IF ANY LABEL/
SCREW IS REMOVED OR BROKEN
P/N: 0A26924 MLC: DA1265
(16383CYL. 16HEADS. 63SEC/T)
0A26924DA12650P5C
S/N: XBGA051E
A$ 80G
NAXP620004H00006
NOT COVER
IS HOLE =>

