

1) The validity of the probe factors in the band of operation can not be determined. The last report cited the factors were valid for up to 1910 MHz. However the calibration data in this report references different tolerances dependent on the type of DASY system configured. Please review as probe factors must be valid from the calibration information in the 1850 – 1910 range.

The Validity of ± 100 MHz only applies for DASY V4.4 and higher.
And, we use DASY version is V4.5, which means probe factors is in the 1710 – 1910 calibration range.