

INTERTEK TESTING SERVICE

Report no.: 0205024

Configuration Photographs

Worst-Case Radiated Emissions

Model : ARKON HP192 (Receiver)

(Front View)



(Back View)

