



Intertek Testing Services

ETL Testing Laboratories

Report No.: 9811024

Tested By: Hong, Report No.: 9811024

Scan Settings (1 Range)


Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten.	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: * QP

Transducer	No.	Start	Stop	Name
	3	9k	30M	EI078

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

dBuV $\diamond$ Mkr : 460.00 kHz 11.6 dBuV



PAGE 1

Ctrl. No.: N/A

FCC ID: MVAR970-001T

Report No.: 9811024

Tested By: Hong, Report No.: 9811024

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: N/A