



Intertek Testing Services

ETL SEMKO

Report No.: 0004225

(Left speaker)

Tested By: Hong, Report No.: 0004225

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0004225

(left speaker)

Tested By: Hong, Report No.: 0004225

Scan Settings (1 Range)

----- Frequencies -----|----- Receiver Settings -----|
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
0.45000	36.1	48.0
0.59000	32.4	48.0
0.78000	29.9	48.0
0.99500	24.1	48.0

* limit exceeded

Ctrl No.: N/A



Intertek Testing Services ETL SEMKO

Report No.: 0004225

(Right speaker)

Tested By: Hong, Report No.: 0004225

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0004225

(Right Speaker)

Tested By: Hong, Report No.: 0004225

Scan Settings (1 Range)

----- Frequencies ----- Receiver Settings -----
Start Stop Step IF BW Detector M-Time Atten Preamp OpRge
450k 30M 5k 10k PK 20ms AUTO LN OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.45000	31.3	48.0
0.59000	26.3	48.0
0.78000	20.6	48.0

* Limit exceeded

Ctrl No.: 2/11