



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

April 26, 2003

RE: FCC ID: MXF-M920403G
Attention: Ellis Wu
/ Alan Lane

I have a few comments on this Application.

1. While you have provided an end user manual on how to set the device up for software operation, you have not provided the OEM installation manual required for the installation information of the device itself into the mobile device. Please provide the OEM installation manual including instructions on installation, warnings of mobile installation only (20 cm separation warning) and FCC notices (changes and modification statement in 15.21 – 2 condition statement in 15.19 – information to user in 15.105).
2. The antenna used in the testing does not appear to have a cable length sufficient to provide a 20 cm separation distance. This means that the OEM installation manual should also warn the OEM installer that the device must be installed within the access point or router in such a way as to allow the antenna to be placed in a minimum 20cm separation distance from the user's body. Please make sure that when you provide the OEM manual this situation is addressed.

Dennis Ward
<mailto:dward@AmericanTCB.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.