


INTERTEK TESTING SERVICES



Internal photos

Base Unit 2141



INTERTEK TESTING SERVICES

Internal photos




Test Report Number: 17071648HKG-001
FCC ID: MZV2-142A
IC: 3912A-2142A

INTERTEK TESTING SERVICES



Internal photos

Base Unit 2142



INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 17071648HKG-001
FCC ID: MZV2-142A
IC: 3912A-2142A

INTERTEK TESTING SERVICES


Internal photos

Handset



INTERTEK TESTING SERVICES



Internal photos



Test Report Number: 17071648HKG-001
FCC ID: MZV2-142A
IC: 3912A-2142A

INTERTEK TESTING SERVICES


Internal photos



Test Report Number: 17071648HKG-001
FCC ID: MZV2-142A
IC: 3912A-2142A

INTERTEK TESTING SERVICES

Internal photos



Test Report Number: 17071648HKG-001
FCC ID: MZV2-142A
IC: 3912A-2142A