



Report No.: 0011593

Tested By: Ben. Report No.: 0011593


Scan Settings (1 Range)

| Frequencies |      |      | Receiver Settings |          |        |       |        |       |
|-------------|------|------|-------------------|----------|--------|-------|--------|-------|
| Start       | Stop | Step | IF BW             | Detector | M-Time | Atten | Preamp | OpRge |
| 450k        | 30M  | 5k   | 10k               | PK       | 20ms   | AUTO  | LN OFF | 60dB  |

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

| Transducer No. | Start | Stop | Name   |
|----------------|-------|------|--------|
| 21             | 9k    | 30M  | EW0698 |





# Intertek Testing Services

## ETL SEMKO

Report No.: 0011593

Tested By: Ben, Report No.: 0011593

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

| Start | Stop | Step | IF BW | Detector | M-Time | Atten | Preamp | OpRge |
|-------|------|------|-------|----------|--------|-------|--------|-------|
|-------|------|------|-------|----------|--------|-------|--------|-------|

|      |     |    |     |    |      |      |    |          |
|------|-----|----|-----|----|------|------|----|----------|
| 450k | 30M | 5k | 10k | PK | 20ms | AUTO | LN | OFF 60dB |
|------|-----|----|-----|----|------|------|----|----------|

Final Measurement Results:

no Results

Ctrl No.: N/A