

Report No.: 9806384

Channel A

Tested By: Hong, Report No.: 9806384

Scan Settings (1 Range)

----- Frequencies ----- | ----- Receiver Settings ----- |

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB


Final Measurement: x QP

Transducer No.	Start	Stop	Name
3	9k	30M	EI078

Meas Time: 1 s

Subranges: 16

Acc Margin: 20dB



Ctrl. No.: N/A

Report No.: 9806384

Channel A

Tested By: Hong, Report No.: 9806384

Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
16.61500	42.6	48.0

* limit exceeded

Ctrl. No.: N/A

Report No.: 9806384

Channel B

Tested By: Hong, Report No.: 9806384


Scan Settings (1 Range)

Frequencies				Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
430k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB	

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
3	9k	30M	EI078



Ctrl. No.: N/A

Report No.: 9806384

channel B

Tested By: Hong, Report No.: 9806384

Scan Settings (1 Range)

----- Frequencies -----			----- Receiver Settings -----					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

Frequency MHz	QP Level dBuV	QP Limit dBuV
16.62500	43.5	48.0

* limit exceeded

Ctrl. No.: N/A