



Intertek Testing Services

ETL SEMKO

Report No.: 9905346
Mode: Charging

Tested Equipment: Report No. 9905346

Scan Settings: 1. Range:

----- Frequency ----- Receiver Settings -----

Start	Stop	Comp	IF BW	Detector	Hi-Time	Atten	Presamp	OPRge
450K	500	SK	10K	PK	10ms	AUTO	LM	OFF

Transducer No.	Start	Stop	Name
3	5K	30M	ET078


Final Measurement: V_{CP}

Name: ET078

Substrate: 14

Amplitude: 10dB

dBm



MHz

PAGE 1

Ctrl. No.:



Intertek Testing Services

ETL SEMKO

Report No.: 9905346

Mode: Charging

Tested By: Hong, Report No.: 9905346

Scan Settings (1 Range)

|----- Frequencies -----| |----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement Results:

no Results

Ctrl. No.: